

1-23-10 Meet Min Subteam Update

Spirit
Working on design for shirt
New Spirit Scheme

Tech Night
ITT New Sponsor might give us shirts

Vaccum
Working on how to make vaccum go over bump
The way the chassis is it hits bump at top and gets stuck vaccum would get hurt

Drive Train
Fix chassis so it goes over bump
tunnel is actually 16 in not 18in = (

Kicker
Electric Motor
In wheel well
swinging
interchangable speeds
Impact in direct center each time

The Arm
gear/spiral lift system
all lift at once not front first = balance

Programming
Educating themselves before actual coding
dave wants a motor set up with encoder